

[5.4] Try Var-Link to fix GraphLink transmission errors

Some ASM programs may crash your calculator, requiring that the batteries be removed. In some cases, GraphLink will not work after this crash. Entering, then exiting the Var-Link screen seems to fix this problem, 100% of the time, according to ZLX. He is using a TI89, AMS 2.05, HW1 and GraphLink 2.0.

(Credit to ZLX)